


1061659-GEAR MOTOR ZIMM MSZ-5-SN



4.2 Checklist - Page 3 - Accessories S
(also see overview chapter 3.3)

Execution:

- SN (standing spindle, normal speed)
- SL (standing spindle, low speed)

Technical drawing showing dimensions and accessory checklist for the ZIMM MSZ-5-SN gear motor assembly.

Dimensions:

- 825
- 145
- 680
- 710
- 50
- 525
- 625

base line ± 0,00

Accessory Checklist:

- Tension load [kn] statically
- Tension load [kn] dynamically
- Compression load [kn] statically
- Compression load [kn] dynamically
- Pivot bearing head
- Forked head
- Rod end
- Fixing flange
- Bellows
- Spiral spring
- Handwheel
- Motor with brake
- Motor without brake
- Coupling
- Rotary pulse encoder
- Mounting bars
- Motor flange
- Safety nut
- Hinged bearing plate
- Limit switch
- Spring pressure brake
- Protective cap
- Lubrication strip
- Protection against rotation
- Escape Protection
- Protective tube
- Linear measuring system